Fluke 718 30G and Fluke 718 100G Pressure **Calibrator Specifications**



<u>Fluke 710 Series Process Calibrators</u> | <u>Product Home</u> | <u>Specifications</u> | <u>Models, Options & Accessories</u> | <u>Manuals</u>

- Function Specifications
- General Specifications

Function Specifications

- инсист ороши	
Measure Pressure (internal sensor)	Range: -12 to 30 psi (-83 to 207 kPa)
Over Pressure 3xFS	Resolution: 0.001 psi (0.01 kPa)
(718 30G only) *	Accuracy: 0.05% full scale
	For use with non-corrosive gasses Zero, Min, Max, Hold, Damp
Measure Pressure	Range: -12 to 100 psi (-83 to 690 kPa)
(internal sensor)	, , ,
Over Pressure 3xFS (718 100G only)	Resolution: 0.01 psi (0.1 kPa)
(710 1000 omy)	Accuracy: 0.05% of full scale
	For use with non-corrosive gasses Zero, Min, Max, Hold, Damp
Measure Pressure	Range: 28 pressure modules, 1.0 in. H20 / 0.25 kPa to
(with Pressure	10,000 psi / 69 Mpa
Modules) Over pressure per	Resolution: To 0.0001 psi, per Pressure Module specs
pressure module	
specs	Accuracy: To 0.05% of full span, per Pressure Module specs
	Note: Media compatibility per Pressure Module Specs,
Carrier Bureaus	Zero, Min, Max, Hold, Damp
Source Pressure, built in pump	Range: -11 psig to full scale
	Resolution: N/A
	Accuracy: N/A
Measure mA	Range: 0 to 24 mA
	Resolution: 0.001 mA
	Accuracy: 0.025% + 1 count
Loop Supply	Range: 24 V dc
	Resolution: N/A
	Accuracy: +/- 10%
	Note: Drive; 20 mA into 1000 Ω for battery >6.8V; 700 Ω for battery 5.8 to 6.8 V

^{*}Supported Pressure Units; psi, in. H20 (4°C), in. H20 (20°C), cm H20 (4°C), cm H20 (20°C), bar, mbar, kPa, inHg, mmHg, kg/cm

General Specifications	
Operating temperature:	-10 C to 55C
Non-operating temperature:	-40 C to 60C
Relative humidity (% RH operating without condensation):	95% (10 C to 30C); 75% (30C to 40C); 45% (40C to 50 C); 35% (50C to 55C)
Operating altitude:	3,000m max
Vibration:	Random, 2g, 5-500 Hz
Shock:	1m drop test
Safety:	CSA C22.2 No. 1010.1:1992
Power:	Single 9V battery ANSI/NEDA 1604A or IEC 6LR61
Size (with holster):	201 mm L x 98mm W x 52 mm D (7.93 in X 3.86 in x 2.06 in)
Weight (with holster):	Approx. 600g (21 oz)
Size (without holster):	187 mm L x 87mm W x 32 mm D (7.35 in X 3.41 in x 1.25 in)
Weight (without holster):	Approx. 330g (12 oz)
Display:	Clear, 5 digit liquid crystal
Warranty:	3 years