




G	SEE ECN #596 FOR CHANGES	SM 03.12.03	TITLE: TWIST—LOK					DWG IN IN (MM)	
F	ADDED FLAME RET. NOTE— ECN #516	SM 11.11.02							
E	ADDED NOTE 3	SJ 03.13.02							
D	CHANGED FILE NO. AND TITLE BLOCK	SM 05.31.01	TOLERANCES UNLESS NOTED .XX=±.010 .XXX=±.005 FRAC=±1/64 ANG=±1°	FILE # TL	DWN: P.B.	APP:	FINAL		
C	RANGE OF 1125 THRU 1750 CHANGED "B" DIM TOLERANCE REMOVED	JP 8/15/94		MAT'L: SEE NOTES	DT: 03—22—94	DT:			
B	P/N TL—600 AND 950 ADDED	PB 8/8/94		RE: RICHCO, INC.	RICHCO INC. PO BOX 804238, CHICAGO, 60680 (773) 539—4060		PART # SEE TABLE	PRINT TYPE CA	
A	P/N TL—1125/1375/1500 AND 1750 ADDED	JP 7/22/94							
REV	DESCRIPTION	ENGR DATE							